

UNDER INVESTIGATION
(SUBSTANDARD)

INVESTIGATION REPORT
DEPARTMENT OF COUNTY ENGINEER
BUILDING AND SAFETY DIVISION
COUNTY OF LOS ANGELES

39 B1

Location of Problem S.G.

Locality 465 Camino Real E/O CALIF

Description of Problem Illegal Construction at the
rear property Gauge conversion

Requested by Grayluong ^(S/G) Phon: 357-6886

Address _____

Received by AR Date 2/24/94

Referred to _____ Date _____

Report of Investigation: _____

Investigator _____ Title _____ Date _____

Copy Sent To _____ Title _____ Date _____

Report Phoned To _____ Title _____ Date _____

8/65

(Not rehab)

REQUEST FOR INVESTIGATION
TO THE DEPARTMENT OF REGIONAL PLANNING

Location 465 E. Camino Real Date 4/6/99
San Gabriel

Complaint Garage conversion to habitable space

Requested by Harry (Complainant)

Address _____ Phone () _____

Submitted by Larry Muro

Address _____

Dept. _____ County of Los Angeles
Building & Safety Division
Phone () _____ 125 S. Baldwin Ave.
Arcadia, CA 91007
(818) 574-0941